# www.WorkshopManuals.co.uk SERVICE BULLETIN

#### SERVICE GROUP, WARRANTY & SERVICE DEP. MITSUBISHI MOTOR SALES EUROPE BV

SERVICE BULLETIN		No.: ESB-96E13-506		
		Date: 1997-02-28	<model></model>	<m y=""></m>
Subject:	CORRECTION TO PROCEDURE FOR EVACUATION OF WATER FROM THE FUEL FILTER		CARISMA	97-10
Group:	FUEL			
Correction		O. Kai - E.V.P. After Sales Service		

## 1. Description:

MITSUBISHI MOTORS

This Service Bulletin informs you that the procedure has been corrected for evacuation of water from the fuel filter.


## 2. Applicable Manual:

Manual	Pub. No.	Language	Page(s)
'97 CARISMA Workshop	PWDE9502-A	(English)	13E-61
Manual chassis SUPPLEMENT	PWDS9503-A	(Spanish)	
	PWDF9504-A	(French)	
	PWDG9505-A	(German)	
	PWDD9506-A	(Dutch)	
	PWDW9507-A	(Swedish)	
	PWDI96E1-A	(Italian)	

## 3. Details:


Please refer to the attached page(s).

Purchased from www.WorkshopManuals.co.uk



- Loosen the drain plug a few turns and tighten the drain plug when clean fuel comes through.
- 6. Bleed the air.

N07B015



Drain plug

#### **EVACUATION OF AIR FROM FUEL LINE**

Bleed the air from the fuel line after refilling the fuel:

- When the fuel is drained for service.
- When fuel filter is replaced.
- When main fuel line is removed.
- 1. Connect a long piece of tubing to the bleedscrew of the fuel injection pump with its open end in a drip tray.
- 2. Open the bleedscrew and operate the pump on the fuel filter until clear fuel flows out of the bleedscrew.
- 3. Close the bleedscrew and remove the tubing.
- 4. Turn the ignition switch to the "ON" position.
- 5. Now pump a few more times until resistance is felt; then pump five more strokes to pressurise the system.
- 6. Start the engine and check for leakage.