

SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

| SERVICE BULLETIN | | No.: MSB-97E16-001 | | | |
|-------------------------------|-----------------------------|--------------------|--|-------------------------|--------------------|
| | | | DATE: 1997-01-15 | <model> CARISMA</model> | <m y=""> 96–10</m> |
| SUBJECT : CHAN GROUP : ENGINE | | | | | |
| INFORMATION | OVERSEAS SERVICE DEPT | 1 | Mamí AMI – MANAGER LITY INFORMATION ANALYSIS | - | |

1. Description:

On the Carisma equipped with the 4G92 SOHC engine and manual transmission and a daytime running lamp, the alternator has been changed in its output current.

2. Effective Date:

From the first production car of 1997 model.

3. Applicable Manual:

Output current:

| Manual | Pub. No. | Page |
|-----------------------------|----------|------|
| '96 CARISMA Workshop Manual | PWDE9502 | 16–3 |

| Λ | П | 0 | ta | i۱ | 0 | |
|----|---|---|----|----|---|--|
| ₹. | u | Œ | La | | J | |

(Old) (New) 70A → 90A