




# SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS  
OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

SERVICE BULLETIN		NO.: MSB-97E16-001		
		DATE: 1997-01-15	<MODEL> CARISMA	<M/Y> 96-10
SUBJECT: CHANGE IN ALTERNATOR OUTPUT CURRENT				
GROUP: ENGINE ELECTRICAL		DRAFTNO.: 96-CH-501		
INFORMATION	OVERSEAS SERVICE DEPT	 R. USAMI - MANAGER QUALITY INFORMATION ANALYSIS		

**1. Description:**

On the Carisma equipped with the 4G92 SOHC engine and manual transmission and a daytime running lamp, the alternator has been changed in its output current.

**2. Effective Date:**

From the first production car of 1997 model.

**3. Applicable Manual:**

Manual	Pub. No.	Page
'96 CARISMA Workshop Manual	PWDE9502	16-3

**4. Details:**

Output current:                      (Old)                      (New)  
   70A                      →                      90A